

Oil Field Environmental Incident Summary

Incident: 20150224152018 **Date/Time of Notice:** 02/24/2015 15:20

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: THOMPSON 44X-20A

Field Name: BLUE BUTTES

Well File #: 30217

Date Incident: 2/24/2015 **Time Incident:** 08:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 95

Sec: 20

Qtr: SE SE

Location Description:

Submitted By: JORDAN WOLF

Received By:

Contact Person: KAYLAN DIRKX
325 22ND AVE E
WILLISTON, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	45	Barrels			80	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/17/2015

Clean Up Concluded: 2/26/2015

Risk Evaluation:

None- spill was stopped immediately and impacted material will be removed.

Areal Extent:

Initial reports indicate saltwater was released off location covering an area approx. 100' x 600'.

Potential Environmental Impacts:

None- spill was stopped immediately and impacted material will be removed.

Action Taken or Planned:

Drilling contractor was reminded of the correct procedure. Landowner was contacted and granted permission to remove impacted topsoil from land.

Wastes Disposal Location: Chimney Butte Disposal

Agencies Involved:

Updates

Date: 2/24/2015 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of fluids flowed off location, apparently during drilling activities. Followup is necessary.

Date: 2/25/2015 **Status:** Inspection

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 1525. Temperature was approximately 18 degrees F with a light wind. Vac trucks were used to collect liquids, and impacted soils were scraped up. LTE environmental consultant Danny Burn was on site to collect confirmation samples. Awaiting confirmation sampling results. If clean, the site will be reseeded in the spring.

Date: 3/19/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 3/19/2015.

Area north of the well impacted by produced water. Area has been scraped. Awaiting cleanup and confirmation samples.

More followup is necessary to ensure proper cleanup.

Date: 3/26/2015 **Status:** Correspondence

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Phone call at 9:22 on 3/26/2015 with company contact.

Samples have been taken, and report is being finalized. When complete, the sampling report and map, along with the determinations, will be sent to the NDDoH, landowner and NDIC for review.

More followup is necessary to ensure cleanup.

Date: 3/27/2015 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received and reviewed the Notice of Completion Report submitted by XTO and LT Environmental. Soil sampling results indicated that remediation was satisfactorily completed. No further action is warranted.